

March Networks Recorder Release 5.11.0 SP1

April 2018

Introduction

March Networks Recorder Release 5.11.0 SP1 consists of maintenance updates for the recorders and the provisioning changes required in the Administrator Console to enable these updates. These release notes describe the updates that have been made to the recorder firmware and provisioning software.

Release 5.11.0 SP1 refers specifically to recorder firmware release 5.11.0.1004.

What Has Changed in Recorder Release 5.11.0 SP1?

Release 5.11.0 SP1 is a maintenance release. See the Resolved Issues table in this document for additional information.





Version Information

If you are planning to upgrade the recorders in your network to release 5.11.0 SP1, you must ensure that the other components of your installation are at the versions in the list below:

Release Line-Up

Software Package	Version	Changed
Command Enterprise	2.3.2.14	Yes
Command Client	2.3.0.8100	No
Command Mobile (download from Apple App Store or Google Play Store)	1.1	No
Command Player	2.3.0.1063	No
Discovery Browser	4.1.3.95	No
Site Manager	3.9.6.82	No
Administrator Console (9000 & 8000 Series, Gen4 4000)	5.11.0.0094	Yes
Recorder Firmware (8724 V)	5.11.0.1004	Yes
Recorder Firmware (9000 Series)	5.11.0.1004	Yes
Recorder Firmware (8000 Series)	5.11.0.1004	Yes
Recorder Firmware (Gen4 4000 Series)	5.8.1.2005	No
Command Recording Server	2.3.0.208	No
Recorder Firmware (6700 Series)	2.4.0	No
Authentication Tool	1.11.1	No
Command SDK	2.3.1.1	No
CRS Active X SDK	2.1.0.63	No
Visual Intelligence ESM	5.11.0.0094	No
Visual Intelligence Clients	5.11.0.0094	No
Visual Intelligence Active X SDK	5.11.0.0094	No

For the list of supported cameras and encoders, please visit the March Networks official website at: https://www.marchnetworks.com/partners/integrations/nvr-integrations/



Resolved Issues

The following issues have been resolved in this release.

Issue ID	Description	Affects
34977	When using "showdisk" the output is now properly formatted and shows all disk information properly.	NVR
35504	Registering a recorder which has a time that is significantly different than the CES time (i.e. > 30 seconds) no longer causes the registration to fail.	NVR
35892	If a recorder disconnects from the CES during a time synchronization sequence, it no longer impacts the ability of the recorder to capture video.	NVR
35988 35991 35993	On recorders that take longer periods of time to perform a systematic shutdown, the recorder now completes the shutdown process properly and no longer experiences a hard power off.	NVR
36042	Seproban functionality now works properly with the 4 and 8 channel recorders.	NVR

Known Issues and Limitations

See the release notes for version 5.11.0.0094 for known issues and limitations.